

# ZYXEL

## Software Release Note Switch XGS1250-12

# **Zyxel Switch XGS1250-12**

## **V1.00(ABWE.2)C0 Release Note**

**Date: Jul. 26, 2021**

---

This document describes the features in the XGS1250 desktop product for its V1.00(ABWE.2)C0 release. Firmware upgrades may reset configuration options to factory default. Please backup your current configuration first before performing firmware upgrade.

### **Supported Platforms**

---

<b>Support Platform</b>	<b>Firmware version</b>
Zyxel XGS1250-12	V1.00(ABWE.2)C0

## New Feature and Enhancements

---

1. Adjust 10G Ethernet port parameter for better overheat protection design. We strongly recommend user to upgrade to the latest firmware to have better overheat protection for Switch with 10G port operation.
2. Support Overheat Protection that prevents the switch from overheating. If any 10Gbps Ethernet copper port overheats for too long without proper ventilation, the port speed will decrease from 2.5G/5G/10G to 1G for switch protection.

## Bug fix

---

1. [eITS#220200586] Switch port is unable to be set as non-member in any VLAN when LAG group is enabled.
2. [eITS#220200586] After changing QoS type to IEEE 802.1p QoS, switch still displays Port-based QoS.
3. [eITS#220301352] Switch port speed will not change even click "Apply" button.

## Known Issue

---

None

## Change History

---

- V1.00(ABWE.2) | 07/26/2022
- V1.00(ABWE.1) | 11/12/2021
- V1.00(ABWE.0) | 03/17/2021