

ZYXEL

Software Release Note Switch XGS1250-12

Date: Dec. 14, 2022

Zyxel Switch XGS1250-12

V1.00(ABWE.3)C0 Release Note

Date: Dec. 14, 2022

This document describes the features in the XGS1250 desktop product for its V1.00(ABWE.3)C0 release. Firmware upgrades may reset configuration options to factory default. Please backup your current configuration first before performing firmware upgrade.

Supported Platforms

Support Platform	Firmware version
Zyxel XGS1250-12	V1.00(ABWE.3)C0

New Feature and Enhancements

1. [eITS#220701389] Add a new Link Aggregation Group for port 9 and port 10.

Bug fix

1. If Link Aggregation Group (LAG) is bound to more than 2 VLANs, the last port of the LAG will be removed after switch reboot.
2. Fixed BN_mod_sqrt() of OpenSSL to cause infinite loop issue by upgrading OpenSSL version.

Known Issue

None

Change History

- V1.00(ABWE.3) | 12/14/2022
- V1.00(ABWE.2) | 07/26/2022
- V1.00(ABWE.1) | 11/12/2021
- V1.00(ABWE.0) | 03/17/2021